



---

## CERTIFICATO DI ISPEZIONE / INSPECTION CERTIFICATE

### N. 23895

---

### FARMALABOR SRL

I – CANOSA DI PUGLIA (BT) – VIA OBERDAN, 52

---

#### UNITA' OPERATIVE/OPERATIVE UNITS

I – CANOSA DI PUGLIA (BT) – VIA MOSCATELLO

I – CANOSA DI PUGLIA (BT) – VIA POZZILLO, Z.I.

---

Con il presente si attesta che l'ispezione ha dato esito positivo relativamente all'applicazione del documento di Farmalabor srl: « **Quality Management and Quality Risk Assessment of the excipient repackaging** » revisione 03 del 10 luglio 2018, che descrive le **Norme di Buona Fabbricazione (NBF)** applicate all'attività di:

*With this document we hereby declare that the Inspection has succeeded with reference to the application of Farmalabor srl « **Quality Management and Quality Risk Assessment of the excipient repackaging** » revision 03, July, 10 2018, which describes the **Good Manufacturing Practices (GMP)** applied to the activity of.*

### Ripartizione di eccipienti farmaceutici

### *Repackaging of pharmaceutical excipients*

Data di Ispezione / Inspection date: 30 agosto 2018

Data di emissione del Certificato di Ispezione / Certificate of Inspection emission date: 05 settembre 2018

Data entro cui avverrà la prossima Ispezione così come indicato nel contratto tra CERTIQUALITY Srl e FARMALABOR srl : 29 agosto 2019

*As defined in the agreement between CERTIQUALITY and FARMALABOR srl, next Inspection should be carried out by: August 29, 2019.*

CERTIQUALITY S.r.l. - Il Presidente/The President

---

Il presente documento è relativo a quanto verificato nel momento e nel luogo dell'ispezione e pertanto CERTIQUALITY Srl non è in alcun modo responsabile di quanto possa avvenire in luoghi o momenti successivi e non assolve FARMALABOR SRL dai suoi obblighi contrattuali nei confronti dei suoi Clienti e dal rispetto delle norme che regolano la sua attività.

L'elenco delle procedure sottoposte a ispezione è riportato in allegato al rapporto di ispezione numero 23895/B del 30 agosto 2018.

*This document is limited to date and place of inspection only and therefore CERTIQUALITY Srl shall not be considered responsible for what could happen in different places or later time. Our inspection does not absolve FARMALABOR SRL from his contractual obligations towards his Clients and from the respect of laws governing its activity.*

*List of verified procedures is reported in annex to inspection report n. 23895/B of August 30, 2018.*

---